




<b>1. COST CENTER: 07</b>  <b>ZT1071</b>  <b>PAN NUMBER</b>   <b>EM00307SAA</b>	<b>ACKNOWLEDGEMENT OF COMPLETION</b> <b>FOR TDD</b> <b>TAT EMERGENCY RESPONSE</b> <b>REMOVAL AND PREVENTION</b> <b>Ecology &amp; Environment</b>	<b>2.. NO.: 07-9203-0012A</b>   <input checked="" type="checkbox"/> <b>COMPLETE</b>  <input type="checkbox"/> <b>INTERIM</b>
<b>3. RESPONSE:</b> THE ECOLOGY & ENVIRONMENT TECHNICAL ASSISTANCE TEAM WAS TASKED BY THE U.S. ENVIRONMENTAL PROTECTION AGENCY EMERGENCY PLANNING AND RESPONSE BRANCH TO ASSESS THE FORMER CERTAIN-TEED TRANSITE PIPE PROPERTY AT 600 ST. CYR ROAD, THE ADJACENT PROPERTY TO SOUTHEAST, AND THE BANKS ALONG MALINE CREEK TO THE SOUTHEAST. THE PURPOSE OF THE ASSESSMENT WAS TO EVALUATE THE EXTENT OF ALLEGED ASBESTOS CONTAMINATION AND SAMPLE SUSPECTED ASBESTOS CONTAINING MEDIUM. THE TAT DOCUMENTED SIGNIFICANT QUANTITIES OF TRANSITE PIPE SCRAP REMAINED ON SITE LARGELY CONCENTRATED ALONG THE STEEP MALINE CREEK BANK SOUTHWEST OF THE FORMER CERTAIN-TEED PROPERTY. IT WAS EVIDENT THAT WEATHERING WAS BREAKING DOWN THE SCRAP, AND EROSION WAS EXPOSING ADDITIONAL SCRAP AND TO A LESSER DEGREE HIGHLY FRIABLE INSULATION MATERIALS ALONG THE CREEK BANK. SAMPLES COLLECTED OF TRANSITE PIPE SCRAP AND INSULATION SHOWED HIGH LEVELS OF ASBESTOS FIBERS - OVER 70% BY VOLUME IN MOST CASES.		<input type="checkbox"/> <b>FORMAL REPORT</b> <input checked="" type="checkbox"/> <b>LETTER REPORT</b> <input type="checkbox"/> <b>FORMAL BRIEFING</b> <input type="checkbox"/> <b>OTHER (SPECIFY)</b>
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> Site: <u>Maline Creek</u>  ID# <u>MOD980631162</u>  Break: <u>22.7</u>  Other: <u>TAT</u>  <u>3-16-92</u> </div>		
<b>3A. INTERIM COST TO DATE :</b> \$5219.60 <b>INTERIM HOURS TO DATE :</b> 74 <b>DATE OF INTERIM AMOUNT:</b> 04/21/92	<b>3B. ACTUAL DIRECT COST :</b> \$ 5494.35 <b>ESTIMATED ADMIN. :</b> <b>EST. COST TO CLOSURE:</b> \$ 5494.86	<b>ACTUAL TOTAL HOURS :</b> 99 <b>DATE OF ACTUAL COSTS:</b> 08/20/92
<b>4. DPO ACTION:</b> <input checked="" type="checkbox"/> <b>ACCEPTED</b> <input type="checkbox"/> <b>ACCEPTED WITH EXCEPTIONS</b> <input type="checkbox"/> <b>REJECTED</b>		
<b>5. COMMENTS:</b>  <div style="text-align: center;"> 07KF  30290716    Superfund  0400  10.0  ES </div>		
<b>6. I CERTIFY THAT THE ATTACHED MATERIALS MEET AND COMPLY WITH ALL REQUIREMENTS OF THE SUBJECT TDD.</b>  <div style="text-align: center;">   (TATL SIGNATURE) </div>		<b>7. DATE:</b> 04/21/92
<b>8. I ACKNOWLEDGE THAT I HAVE BEEN PROVIDED WITH THE MATERIALS AND SERVICES SPECIFIED IN THE SUBJECT TDD WITHIN ITS ORIGINAL OR REVISED TIME FRAMES.</b>  <div style="text-align: center;">   (AUTHORIZING DPO SIGNATURE) </div>		<b>9. DATE:</b> 09/20/92

**Distribution:**

DPO Copy	PO Copy
TATL Copy	CO Copy
ZPM Copy	DPO Original